

Process Sheet

Drawing Name

: TUBE END PLATE

S.O. No. :

Part Number

: PB6743001111

Drawing Number

- B67-43001 P.32

Project Number **Drawing Revision**

: N/A : B1

Material

: 01/07/2008

Due Date

Qty:

5 Um:

Each

: SMALL /MED FAB

08.06.19 DD verified: EC



Seq. #:

Machine Or Operation:

Description:

6061-T6 .125 Sheet

Comment: Qty.:

M6061T6S125

0.0164 sf(s)/Unit Total: 0.0819 sf(s)

6061-T6 .125Sheet 106634 batch:-

2.0

1.0

WATER JET









Comment: FLOW WATER JET

1-Cut as per Dwg B67-43001

Dwa Rev:

Prog Rev:___

2-Deburr if necessary

≥ 08/06/25 INSPECT PARTS AS THEY COME OFF MACHINE

3.0

B 8-6-25


Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

SECOND CHECK



Comment: SECOND CHECK



PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location:

mi 08-07-09

Dart Aerospace Ltd

W/O:	·	WORK ORDER CHA	ANGES
DATE STEP		PROCEDURE CHANGE	By Date Qty Approval Chief Eng / Prod Mgr QC Inspector
		1	

Part No:	PAR #:	Fault Category: _	i	NCR: Yes No	DQA:	Date:
				QA: N/C C	losed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
		Description of NC	Corrective Action Section B			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	A	AI
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
				1				
				I .		•		
				1				
				1				
								3

NOTE: Date & initial all entries

Date:

Tuesday, 24/06/2008 11:30:24 AM

User:

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: TUBE END PLATE

Job Number: 40013

Part Number: PB6743001111

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE





08/07/10 HJ MF 08-07-09

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion




Dart Aerospace Ltd

W/O:		WORK ORDER CH	HANGES
DATE	STEP	PROCEDURE CHANGE	By Date Qty Approval Chief Eng / Prod Mgr QC Inspector
	L		

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
			QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						=
		Description of NC		Corrective Action Section B		Verification	A	A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
							·	
				1				
				1				
				ı				
				I				
				ı				
				T.				
				T.				•

NOTE: Date & initial all entries



-DART AEROSPACE LTD	Work Order:	40013
Description: TUBE FUD DLATE	Part Number:	PB 6743001-11
Inspection Dwg: Rev: 6		Page 1 of 1

PB 674 3001-111 Pg 32 FIRST ARTICLE INSPECTION CHECKLIST

X First Article	Prototype
-----------------	-----------

Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
4- 130	1.500	X-		Jorn	
11		×		ven	
	<u> </u>				
	· · · · · · · · · · · · · · · · · · ·				
		`			
	4010	Tolerance Dimension 1.500 1.500 1.30	Tolerance Dimension () (Tolerance Dimension Accept Reject	Tolerance Dimension Accept Reject Inspection 1.500 F John 1.70 F Joh

		<u> </u>			
Measured by: IR	Audited by:	8,,	Prototype Approval:	a	
Date: 8-6-26	Date:	08/06/20	Date:	1	<u>+</u>

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	<u> </u>